

Suggestion A

Description of the suggestion

- Full renovation of the inside of the pool. Mosaic will be removed and replaced with new tiles.
- Partly renovation of the pool area, broken tiles will be changed, including floor and shower area.
- New staircase in concrete/tiles will be established in the corner of the pool next to the shower, this will make the pool more accessible.

Specifics

Color: Same as previous

Tiles: Pool - bigger tiles as the small mosaic easily brake and adds to our maintenance budget (Dolphin will not be replaced due to this)Surrounding pool area – same as previous

New: Staircase

Price range : 5000 Euro

Note: This figure is calculated as an estimate, so it could change when implementing the project due to the high inflation in Turkey.



Suggestion B

Description of the suggestion:

- Full renovation of the inside of the pool. Mosaic will be removed and replaced with new tiles.
- Full renovation of the pool area, broken tiles will be changed. (Including floor and shower)
- New staircase will be established

Specifics

Colour: Sand/light

Tiles: Larger tiles in the pool

New: Staircase

- Tiles: Price range : 7000 – 7500 Euro

Note: This figure is calculated as an estimate, so it could change when implementing the project due to the high inflation in Turkey.



Suggestion C

Description of the suggestion

Full renovation of the inside of the pool. Mosaic will be removed and replaced with new tiles.

Full renovation of the pool area, broken tiles will be changed. Including floor and shower.

New staircase will be established

All sunbeds and umbrellas will be replaced with new wooden furniture

Specifics

Colour: Sand/light

New: Staircase and common furniture

Tiles: Bigger tiles in the pool

Price range : 10 000 Euro

Note: This figure is calculated as an estimate, so it could change when implementing the project due to the high inflation in Turkey.



Staircase examples

